## IN THE UNITED STATES PATENT & TRADEMARK OFFICE

ATTORNEY DOCKET NUMBER: 10003439-1

IN RE APPLICATION OF: U.S. Patent No. 7,068,073

**USPTO CONFIRMATION CODE: 6675** 

APPLICATION NO.: 09/811,192

FILED: Mar. 17, 2001

EXAMINER: James H. Cho

**GROUP ART UNIT: 2819** 

FOR: CIRCUIT FOR SWITCHING ONE OR MORE HVD TRANSCEIVERS

## 37 CFR 1.322 & 37 CFR 1.323 REQUEST FOR CERTIFICATE OF CORRECTION

## HONORABLE COMMISSIONER OF PATENTS & TRADEMARKS

Sir:

The following is a request for a certificate of correction in Serial Number 09/811,192, now Patent Number 7,068,073.

A certificate of correction under 35 USC 254 is respectfully requested in the above-identified patent.

All errors were the fault of the USPTO, no fee required. In the event that a further fee is required, please charge the amount to Deposit Account No. 082025.	r
All errors were the fault of the applicant and, accordingly, please charge \$100.00 to our Deposit Account No. 082025. In the event that a further fee is required, please charge the amount to the same Deposit Account.	2
The errors were the fault of both the applicant and USPTO and, accordingly, please charge \$100.00 to our Deposit Account No. 082025. In the event that a further fe is required, please charge the amount to the same Deposit Account.	e

The exact locations where the errors appear in the patent and patent application are as follows:

On the face page, in field (56), under "Foreign Patent Documents", in column 2, line 1, delete "DE" and insert - - EP - -, therefor. (List of references cited by examiner dated Jul. 14, 2004, page 1 of 1, under "Foreign Patent Documents", entry 1)

The requested corrections are attached on Form PTO 1050.

Respectfully Submitted

3-APR-2009

DATE

Michael S. Czarnecki

Registration No.: 61,257

Attorney/Agent of Record

HEWLETT-PACKARD COMPANY Intellectual Property Administration P.O. Box 272400 Fort Collins, Colorado 80527-2400